




Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.



Recorded by Deirdre Brotherson

Organization Kingston Historical Commission

Date (month/year) March 2002

s number _____ USGS Quad _____ Area(s) _____ Form Number KIN.440
 _____ Plymouth _____ 440

Town Kingston

Place (neighborhood or village) Main Street

Address 202 Main Street

Historic Name _____

Uses: Present residence

Original residence

Date of Construction 1938

Source Assessor's Office files

Style/Form cape

Architect/Builder _____

Exterior Material:

Foundation concrete

Wall/Trim wood shingle

Roof asphalt shingles

Outbuildings/Secondary Structures _____

Major Alterations (with dates)

1970 chimney; 1992 addition

Condition good

Moved no yes Date _____

Acreage 14,374 sf

Setting set back from Main Street in wooded setting

RECEIVED

BFC 14 2002

MASS. HIST. COMM.

BUILDING FORM

KIN. 440

ARCHITECTURAL DESCRIPTION *see continuation sheet*

Describe architectural features Evaluate the characteristics of this building in terms of other buildings within the community.

The residence at 202 Main Street was built in 1938 as a cape with a side gable roof. This 3 x 2 bay, wood frame, one-and-a-half story building is rectangular in plan and sits on a concrete foundation. The building is clad with wood shingles. The side gable roof is covered with asphalt shingles. Two single dormers pierce the roof on the front and a shed dormer runs across the rear of the house. One brick chimney is located in the center of the house. The center entrance contains a wood panel door with a plain surround. An arched trellis protects this front entrance. The windows contain 6/6 wood sash with flat surrounds. A bay window protrudes from the side of the first floor. The cornerboards are thin and flat. The cornice is thin with a shallow molding.

A side ell, built in 1992 is attached to the side of the house and is of similar construction. An attached shed is also part of this addition.

HISTORICAL NARRATIVE *see continuation sheet*

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

According to assessors records this house was built in 1938 in 14,374 sf of land. In 1970 the chimney was added or altered and in 1992 the side addition was built.

The records list only one owner, James M. and Jayne L. Darsch.

BIBLIOGRAPHY and/or REFERENCES *see continuation sheet*

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*

MHC INVENTORY FORM CONTINUATION SHEET

MHC Inventory scanning project, 2008-2012

MACRIS No. KIN 440

