



s number _____ USGS Quad _____ Area(s) _____ Form Number KIN.450
 _____ Plymouth B 450

Town Kingston

Place (neighborhood or village)
Main Street

Address 256 Main Street

Historic Name _____

Uses: Present residence
Original residence

Date of Construction 1890

Source Assessor's Office files

Style/Form Italianate

Architect/Builder _____

Exterior Material: _____

Foundation concrete block

Wall/Trim vinyl siding

Roof asphalt shingles

Outbuildings/Secondary Structures

Major Alterations (with dates)
original entrance removed, vinyl siding


Condition fair

Moved no yes Date _____

Acreage 17,424 sf

Setting
linear neighborhood, Main Street

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.



Recorded by Deirdre Brotherson

Organization Kingston Historical Commission

Date (month/year) March 2002

RECEIVED

DEC 14 2005

MASS. HIST. COMM.

ARCHITECTURAL DESCRIPTION *see continuation sheet*

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings within the community.

The residence at 256 Main Street was built in 1890 in the Italianate style with a front gable roof. This 3 x 4 bay, wood frame, two story building is rectangular in plan and sits on a concrete block foundation. The building is clad with vinyl siding. The front gable roof is covered with asphalt shingles. Two brick chimneys are located at the ridge of the house. The side entrance contains wood door with a plain surround. The windows contain 6/6 wood sash with no surrounds. A bay window projects from the front of the building. The cornice is thin with a shallow molding. A side and rear ell are attached to this building.

HISTORICAL NARRATIVE *see continuation sheet*

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

Unfortunately, this house has been heavily altered and has lost much of its architectural integrity. It appears that the original front entrance has been covered or removed. All of the original trim has also been covered or removed.

The house was built in 1890 and the current owner is the Doris Dandeneau Trust.

BIBLIOGRAPHY and/or REFERENCES *see continuation sheet*

Recommended for listing in the National Register of Historic Places.

If checked, you must attach

a completed National Register Criteria Statement form.

MHC INVENTORY FORM CONTINUATION SHEET

MHC Inventory scanning project, 2008-2012

MACRIS No. KIN.450



KIN.450



256 Main St.

10011