

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.



Organization <u>Kingston Historical Commission</u> Date (month/year) <u>March 2002</u>

KIN.452	
number USGS Quad Area(s) Form Number	
Plymouth B 452	
Town Kingston	
Place (neighborhood or village) Main Street	
Address 263 Main Street	
Historic Name	
Uses: Present residence	
Original residence	
Date of Construction 1902	
Source Assessor's Office files	
Style/Form vernacular	
Architect/Builder	
Exterior Material:	
Foundation brick	
Wall/Trim wood clapboard	
Roof asphalt shingles	
Outbuildings/Secondary Structures garage 1981	
Major Alterations (with dates)	
·····	
Condition good	
Moved Into I yes Date	-
Acreage 43,522 sf	
Setting DEC 14 200	5
linear neighborhood, main Street, near intersection	17.54

Follow Massachusetts Historical Commission Survey Manual instructions when completing this form.

Describe architectural features Evaluate the characteristics of this building in terms of other buildings within the community.

The residence at 263 Main Street was built in 1902 in the vernacular style with a front gable roof. This 3 x 4 bay, wood frame, two story building is rectangular in plan and sits on a brick foundation. The building is clad with wood clapboards. The front gable roof is covered with asphalt shingles. One brick chimney is located on the rear slope of the roof. The off-center entrance contains a wood door with a glass panel flanked by a sidelight on one side with a plain surround. The windows contain vinyl replacement sash with flat surrounds and a molded cap. The cornerboards are thin and flat. The cornice is thin with a shallow molding. The windows on the side elevation have been altered and condensed into one large window.

A two stall garage built in 1981 sits to the rear of the building.

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

This house was built in 1902. The windows have been altered indicating interior alterations as well. The garage was added in 1981. The present owner is Nancy Burchill.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

☐ Recommended for listing in the National Register of Historic Places. *a completed National Register Criteria Statement form.* If checked, you must attach

7/92

KIN.452

MHC INVENTORY FORM CONTINUATION SHEET *MHC Inventory scanning project, 2008-2012*

MACRIS No. KIN. 452